









3000 pneumatik / 1 den
KONFEKCE CVT 53 x 89 m



SAV 1, 2, 3 - 17,5" 20" 22,5"	SAV 4, 7 - 20" 22,5" 24"	SAV 5, 6, 8, 9 - 17,5"
PL/G - 18" 20"	PU 8, KM 12/15i - 8" 9" 10" 12" 15" 16"	KM 88i, K-unit - 8" 9" 10" 12" 15" 16"

-  **KM 88 i, K-unit Barum**
-  **SAV 5, 6, 8, 9**
-  **SAV 1, 2, 3, 4, 7, PL/G**

-  **SAV 6, 8, 9**
-  **SAV 1, 2, 3, 4, 5, 7, KPL**
-  **KM 88i, K-unit, KM 12/15i, PU**



GRADER, OPRAVY VNITŘNÍ GUMY, OPRAVY PATEK



INSPEKTOMATY